

| Worked on in 2022 | Worked on in 2021 | Worked on in 2020 | Road Tree is On | Tree ID Tag Number | (Diameter 4.5' above grade) | Common Name | Address Number | Street Name | Approximate Location | Priority Rating: | Size of material to be removed 1-3. 1 is smallest size | Remove Tree; Haul all debris | Crown Clin Dead | Structure prune to remove crossing/crowded branch unions and where needed co-dominant lead correction | End weight reduce over-extended limbs likely to fail | Install total of ___ direct cable systems for supplemental support of weak attachments | Remove Broken Leads, Hangers and / or stubs | Crown Raise over Road & Parking to Approx. 12' | Crown Raise to Approx. 6-8' over Walk / Lawn / Roof / Lights | Remove all upright watersprouts and train horizontal | Major Health Decline / Dead | Decay and/or Hollow Detected | Multiple trunks | Included Bark | Girdling Roots | Additional Notes |
|-------------------|-------------------|-------------------|-----------------|--------------------|-----------------------------|-------------------|----------------|-------------|----------------------|------------------|--|------------------------------|-----------------|---|--|--|---|--|--|--|-----------------------------|------------------------------|-----------------|---------------|----------------|------------------|
| | | | G | 37 | | Open Planting Pit | 700 | Greenhill | FL | | | | | | | | | | | | | | | | | |
| | | | G | 38 | 24 | Willow Oak | 700 | Greenhill | FR | | | | | | | | | | | | | | | | | |
| | | | B | 39 | 22 | Sugar Maple | 700 | Blackshire | FR | A | 1 | x | | | | | | | | | | | | | | |
| | | | B | 40 | 10 | Kentucky Coffee | 701 | Blackshire | FL | | | | | | | | | | | | | | | | | |
| | | | B | 41 | 12 | Red Maple | 702 | Blackshire | FR | B | 1 | | x | | | | | | | | | | | | | |
| | | | B | 42 | 12 | Red Maple | 701 | Blackshire | FR | C | 1 | | | | | | | | | | | | | | Storm damage | |
| | | | B | 43 | 16 | Sugar Maple | 704 | Blackshire | FM | | | | | | | | | | | | | | | | | |
| | | | B | 44 | 2 | Golden Rain Tree | 706 | Blackshire | FL | C | 1 | | | | | | x | x | | | | | | | | |
| | | | B | 45 | | Open Planting Pit | 710 | Blackshire | FR | | | | | | | | | | | | | | | | | |
| | | | B | 46 | | Open Planting Pit | 707 | Blackshire | FL | | | | | | | | | | | | | | | | | |
| | | | B | 47 | 12 | Red Maple | 710 | Blackshire | FL | B | 2 | | x | | | | | | | | | | | | | |
| | | | B | 48 | 22 | Sugar Maple | 712 | Blackshire | FR | | | | | | | | | | | | | | | | | |
| | x | | B | 49 | 36 | Zelkova | 707 | Blackshire | FR | B | 3 | | | | | | | x | | | | | | | | |
| | | | B | 50 | | Open Planting Pit | 709 | Blackshire | FL | | | | | | | | | | | | | | | | | |
| | | | B | 51 | 2 | Tree Lilac | 714 | Blackshire | FM | | | | | | | | | | | | x | | | | | |
| | | | B | 52 | 24 | Ginko | 709 | Blackshire | FR | A | 2 | x | | | | | | | | | | | | | | |
| | | | B | 53 | 12 | Red Maple | 716 | Blackshire | FR | B | 2 | | x | | | x | x | x | | | x | x | | | | |
| | | | B | 54 | 6 | Red Maple | 711 | Blackshire | FR | C | 2 | | x | | | | x | x | | | | | | | | |
| | | | B | 55 | 12 | Red Maple | 718 | Blackshire | FM | B | 2 | | x | | | | x | x | | | x | x | | | | |
| | | | B | 56 | 12 | Red Maple | 722 | Blackshire | FM | B | 2 | | x | | | x | | | | | x | x | | | Storm damage | |
| | | | B | 57 | 16 | Sugar Maple | 2 | Bedford | RB | A | 1 | x | | | | | x | x | | | | | | | | |
| | | | B | 58 | 24 | Sugar Maple | 715 | Blackshire | FL | A | 2 | x | x | x | | | x | x | | | | | | | | |
| | | | B | 59 | 4 | Red Maple | 2 | Bedford | RF | B | 1 | | x | | | | x | x | | | | | | | | |
| | | | B | 60 | 16 | Red Maple | 715 | Blackshire | FM | B | 2 | | | x | | | x | x | | | | | | | | |
| | | | B | 61 | 18 | Sugar Maple | 717 | Blackshire | FR | A | 1 | x | x | | | | | | | | | x | x | | | |
| | | x | B | 62 | 14 | Sugar Maple | 30 | Bedford | LB | A | 1 | x | | | | | | | | | | | | | | |
| | | | B | 63 | 8 | Red Maple | 719 | Blackshire | FL | B | 1 | | x | | | | x | x | | | | | | | | |
| | | | B | 64 | 22 | Sugar Maple | 800 | Blackshire | FL | A | 2 | x | | | | | | | | | | | | | | |
| | x | | B | 65 | 26 | Zelkova | 719 | Blackshire | FR | A | 1 | x | | | | | | | | | | | | | | |
| | | | B | 66 | 10 | Red Maple | 802 | Blackshire | FR | B | 2 | | x | | | | x | | | | | | | | | |
| | | | B | 67 | 24 | Sugar Maple | 721 | Blackshire | FM | A | 1 | x | | | | | | | | | | | | | | |
| | | | B | 68 | 18 | Sugar Maple | 802 | Blackshire | FL | A | 1 | x | | | | | | | | | | | | | | |
| | | | B | 69 | 3 | Red Maple | 806 | Blackshire | FM | C | 1 | | | | | | x | x | | | | | | | | |
| | | | B | 70 | 22 | Sugar Maple | 723 | Blackshire | FM | A | 2 | x | | | | x | x | x | | | | | | | | |
| | | | B | 71 | 6 | Black Gum | 2300 | Seymoure | LB | B | 2 | | x | | | | x | x | | | | | | | | |
| | | | B | 72 | 3 | Black Gum | 808 | Blackshire | FM | | | | | | | | | | | | | | | | | |
| | | | B | 73 | 3 | Black Gum | 810 | Blackshire | FM | C | 1 | | | | | | x | x | | | | | | | | |

| Worked on in 2022 | Worked on in 2021 | Worked on in 2020 | Road Tree is On | Tree ID Tag Number | (Diameter 4.5' above grade) | Common Name | Address Number | Street Name | Approximate Location | Priority Rating: | Size of material to be removed 1-3. 1 is smallest size | Remove Tree; Haul all debris | Crown Clin Dead | Structure prune to remove crossing/crowded branch unions and where needed co-dominant lead correction | End weight reduce over-extended limbs likely to fail | Install total of ___ direct cable systems for supplemental support of weak attachments | Remove Broken Leads, Hangers and / or stubs | Crown Raise over Road & Parking to Approx. 12' | Crown Raise to Approx. 6-8' over Walk / Lawn / Roof / Lights | Remove all upright watersprouts and train horizontal | Major Health Decline / Dead | Decay and/or Hollow Detected | Multiple trunks | Included Bark | Girdling Roots | Additional Notes |
|-------------------|-------------------|-------------------|-----------------|--------------------|-----------------------------|-------------------|----------------|-------------|----------------------|------------------|--|------------------------------|-----------------|---|--|--|---|--|--|--|-----------------------------|------------------------------|-----------------|---------------|----------------|------------------|
| | | | N | 188 | 4 | Red Maple | 728 | Nottingham | FM | B | 1 | | | x | | | | x | x | | | | | | | |
| | | | N | 189 | 24 | Zelkova | 727 | Nottingham | FR | A | 1 | x | | x | | | | x | x | | | | | | | |
| | | | N | 190 | | Open Planting Pit | 731 | Nottingham | FR | | | | | | | | | | | | | | | | | |
| | | | N | 191 | | Open Planting Pit | 726 | Nottingham | FL | | | | | | | | | | | | | | | | | |
| | | | N | 192 | 18 | Sugar Maple | 727 | Nottingham | FM | | | | | | | | | | | | | | | | | |
| | | | N | 193 | 12 | Sugar Maple | 726 | Nottingham | FR | | | | | | | | | | | | | | | | | |
| | | x | N | 194 | 12 | Sugar Maple | 727 | Nottingham | FL | A | 1 | x | | | | | | | | | | | | | | |
| | | | N | 195 | 8 | Red Maple | 722 | Nottingham | FM | B | 3 | | | x | | | | | | | | x | x | | | |
| | | x | N | 196 | 2 | American Hornbeam | 723 | Nottingham | FR | | | | | | | | | | | | | | | | | |
| | | | N | 197 | 18 | Sugar Maple | 720 | Nottingham | FM | A | 1 | x | | | | | | | | | | | | | | |
| | | x | N | 198 | | Open Planting Pit | 723 | Nottingham | FL | | | | | | | | | | | | | | | | | |
| | | | N | 199 | 24 | Sugar Maple | 721 | Nottingham | FM | C | 3 | | | | | x | | x | | | | | | | | |
| | | | N | 200 | 16 | Sugar Maple | 716 | Nottingham | FM | A | 1 | x | | | | | | | | | | | | | | |
| x | | | N | 201 | 16 | Sugar Maple | 719 | Nottingham | FM | A | 1 | x | | | | | | | | | x | | | | | x |
| x | | | N | 202 | 12 | Sugar Maple | 717 | Nottingham | FM | A | 1 | x | | | | | | | | | | | | | | x |
| x | x | | N | 203 | 12 | Red Maple | 714 | Nottingham | FM | | | | | | | | | | | | | | | | | |
| | | | N | 204 | 12 | Red Maple | 715 | Nottingham | FM | B | 3 | | | x | | | | | | | | x | x | | | |
| | | | N | 205 | 20 | Sugar Maple | 712 | Nottingham | FM | A | 2 | x | | | | | | | | | | | | | | |
| | | | N | 206 | 12 | Sugar Maple | 713 | Nottingham | FR | A | 2 | x | | | | | | | | | | | | | | |
| | | | N | 207 | 12 | Red Maple | 710 | Nottingham | FL | | | | | | | | | | | | | | | | | |
| | | | N | 208 | 10 | Red Maple | 710 | Nottingham | FM | C | 2 | | | | | | | x | x | | | | | | | |
| | | x | N | 209 | 20 | Elm | 713 | Nottingham | FL | A | 1 | x | | x | | | | | | x | | x | x | | | |
| x | | x | N | 210 | 24 | Elm | 710 | Nottingham | FR | | | | | | | | | | | | | | | | | |
| | | | N | 211 | 24 | Zelkova | 709 | Nottingham | FM | A | 2 | x | | | | | | | | | | | | | | |
| | | x | N | 212 | 30 | Zelkova | 706 | Nottingham | FM | A | 1 | x | | | | | | | | | | | | | | |
| | | | N | 213 | 16 | Sugar Maple | 706 | Nottingham | FR | A | 1 | x | | | | | | | | | | | | | | x |
| | | x | N | 213 | 30 | Zelkova | 707 | Nottingham | FR | | | | | | | | | | | | | | | | | Storm damage |
| | | | N | 214 | 16 | Zelkova | 707 | Nottingham | FL | | | | | | | | | | | | | | | | | |
| | | | N | 215 | 36 | Zelkova | 704 | Nottingham | FM | A | 2 | x | | | | | | | | | | | | | | |
| | | | P | 216 | 4 | Redbud | | Palmer Sq | Island | | | | | | | | | | | | | | | | | |
| | | | P | 217 | 4 | Redbud | | Palmer Sq | Island | | | | | | | | | | | | | | | | | |
| | | | P | 218 | 4 | Redbud | | Palmer Sq | Island | | | | | | | | | | | | x | | | | | |
| | | | C | 219 | 12 | Bradford Pear | 701 | Blackshire | RF | | | | | | | | | | | | | | | | | Consider removal |
| | | | C | 220 | 12 | Zelkova | 700 | Coverdale | FR | A | 2 | x | | | | | | | | | | | | | | |
| | | | C | 221 | 8 | American Linden | 701 | Blackshire | RM | B | 2 | | | x | | | | x | x | | | | | | | |
| | | | C | 222 | 20 | Zelkova | 700 | Coverdale | FL | A | 1 | x | | | | | | | | | | | | | | |
| | | | C | 223 | 6 | American Linden | 701 | Blackshire | RB | B | 3 | | | x | | | | x | x | | | | | | | |

| Worked on in 2022 | Worked on in 2021 | Worked on in 2020 | Road | Tree ID | Tag Number | (Diameter 4.5' above grade) | Common Name | Address Number | Street Name | Approximate Location | Priority Rating: | Size of material to be removed 1-3. 1 is smallest size | Remove Tree; Haul all debris | Crown Clin Dead | Structure prune to remove crossing/crowded branch unions and where needed co-dominant lead correction | End weight reduce over-extended limbs likely to fail | Install total of ___ direct cable systems for supplemental support of weak attachments | Remove Broken Leads, Hangers and / or stubs | Crown Raise over Road & Parking to Approx. 12' | Crown Raise to Approx. 6-8' over Walk / Lawn / Roof / Lights | Remove all upright watersprouts and train horizontal | Major Health Decline / Dead | Decay and/or Hollow Detected | Multiple trunks | Included Bark | Girdling Roots | Additional Notes | |
|-------------------|-------------------|-------------------|------|---------|------------|-----------------------------|---------------------|----------------|-------------|----------------------|------------------|--|------------------------------|-----------------|---|--|--|---|--|--|--|-----------------------------|------------------------------|-----------------|---------------|----------------|------------------|--|
| | x | | W 11 | 371 | 30 | | Zelkova | 2311 | W 11th | FR | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 372 | 6 | | White Oak | 2311 | W 11th | FR | C | 2 | | | | | | | | | | | | | | | | |
| | | | W 11 | 373 | 3 | | Redbud | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | x | | W 11 | 374 | 40 | | Willow Oak | 3210 | W 11th | FL | A | 1 | | | | | | | | | | | | | | | | |
| | | | W 11 | 375 | 24 | | Sugar Maple | 2308 | W 11th | FR | A | 3 | x | | | | | | | | | | | | | | | |
| | | | W 11 | 376 | 3 | | Redbud | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 376 | 3 | | Redbud | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 377 | 6 | | Red Oak | 2305 | W 11th | FL | C | 2 | | | | | | | | | | | | | | | | |
| | | | W 11 | 378 | 20 | | Red Oak | 2305 | W 11th | FM | C | 2 | | | | | | | | | | | | | | | | |
| | | | W 11 | 379 | | | Open Planting Pit | 2308 | W 11th | FL | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 380 | 3 | | Black Gum | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 381 | 3 | | Witch Hazel | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 382 | 16 | | Red Oak | 2305 | W 11th | FR | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 383 | 8 | | Kentucky Coffee | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 384 | 3 | | Witch Hazel | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 385 | 30 | | Willow Oak | 2304 | W 11th | FR | A | 3 | | | | | | | | | | | | | | | | |
| | | | W 11 | 386 | 28 | | Willow Oak | 2304 | W 11th | FL | A | 2 | | | | | | | | | | | | | | | | |
| | | | W 11 | 387 | 24 | | Willow Oak | | W 11th | Island | A | 2 | | | | | | | | | | | | | | | | |
| | x | | W 11 | 388 | 30 | | Willow Oak | 2303 | W 11th | FL | A | 3 | | | | | | | | | | | | | | | | |
| | | | W 11 | 389 | 4 | | Witch Hazel | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 390 | 3 | | White Oak | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 391 | 30 | | Willow Oak | 2303 | W 11th | FR | A | 3 | | | | | | | | | | | | | | | | |
| | | | W 11 | 392 | 25 | | Willow Oak | | W 11th | Island | A | 2 | | | | | | | | | | | | | | | | |
| | x | | W 11 | 393 | 30 | | Willow Oak | 2302 | W 11th | FM | A | 1 | | | | | | | | | | | | | | | | |
| | | | W 11 | 394 | 4 | | Kentucky Coffee | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 395 | 12 | | Horse Chestnut | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 396 | 30 | | Willow Oak | 913 | Blackshire | RB | A | 3 | | | | | | | | | | | | | | | | |
| | x | | W 11 | 396 | 30 | | Willow Oak | 2301 | W 11th | FM | | | | | | | | | | | | | | | | | | |
| | x | | W 11 | 397 | 36 | | Willow Oak | | W 11th | Island | A | 1 | | | | | | | | | | | | | | | | |
| | x | | W 11 | 398 | 40 | | Willow Oak | 913 | Blackshire | RF | A | 3 | | | | | | | | | | | | | | | | |
| | | | W 11 | 399 | 4 | | Carolina Silverbell | | W 11th | Island | B | 1 | | | | | | | | | | | | | | | | |
| | | | W 11 | 400 | 30 | | Willow Oak | 2301 | W 11th | FR | A | 3 | | | | | | | | | | | | | | | | |
| | | | W 11 | 401 | 12 | | Japanese Maple | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| x | | | W 11 | 402 | 36 | | Willow Oak | 1100 | Blackshire | RF | A | 1 | | | | | | | | | | | | | | | | |
| | | | W 11 | 403 | 3 | | Redbud | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 404 | 3 | | Redbud | | W 11th | Island | | | | | | | | | | | | | | | | | | |
| | | | W 11 | 404 | 3 | | Redbud | | W 11th | Island | | | | | | | | | | | | | | | | | | |

Dead Warrenty

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----------------------|-------------------|-------------------|-----------------|--------------------|-----------------------------|-------------|----------------|-------------|----------------------|------------------|--|------------------------------|-------------------------------|---|--|--|---|--|--|--|-----------------------------|------------------------------|-----------------|---------------|----------------|------------------|
| Worked on in 2022 | Worked on in 2021 | Worked on in 2020 | Road Tree is On | Tree ID Tag Number | (Diameter 4.5' above grade) | Common Name | Address Number | Street Name | Approximate Location | Priority Rating: | Size of material to be removed 1-3. 1 is smallest size | Remove Tree; Haul all debris | Crown Cln Dead ___ " and Lgrs | Structure prune to remove crossing/crowded branch unions and where needed co-dominant lead correction | End weight reduce over-extended limbs likely to fail | Install total of ___ direct cable systems for supplemental support of weak attachments | Remove Broken Leads, Hangers and / or stubs | Crown Raise over Road & Parking to Approx. 12' | Crown Raise to Approx. 6-8' over Walk / Lawn / Roof / Lights | Remove all upright watersprouts and train horizontal | Major Health Decline / Dead | Decay and/or Hollow Detected | Multiple trunks | Included Bark | Girdling Roots | Additional Notes |
| Totals of each column | | | | | | | | | | | 2 | 170 | 53 | 7 | 4 | 10 | 73 | 80 | 3 | | | | | | | |

| | |
|-----------------------|-----|
| Ash; White | 1 |
| Bald Cypress | 2 |
| Boxelder | 1 |
| Chestnut; Horse | 1 |
| Dogwood; Flowering | 1 |
| Dogwood; Kousa | 3 |
| Elm | 3 |
| Ginko | 4 |
| Gum; Black | 5 |
| Gum; Fastigeous Sweet | 1 |
| Golden Rain Tree | 1 |
| Hornbeam; American | 6 |
| Kentucky Coffee | 9 |
| Linden; American | 3 |
| Maple; Japanese | 1 |
| Maple; Red | 36 |
| Maple; Sugar | 54 |
| Maple; Trident | 0 |
| Oak; Burr | 0 |
| Oak; Chestnut | 1 |
| Oak; Fastigeous White | 5 |
| Oak; Laurel | 2 |
| Oak; Pin | 4 |
| Oak; Red | 6 |
| Oak; Southern Red | 1 |
| Oak; White | 9 |
| Oak; Willow | 110 |
| Open Planting Pit | 35 |
| Pear; Bradford | 16 |
| Redbud | 10 |
| Stump | 0 |
| Silverbell, Carolina | 1 |
| Tree Lilac | 1 |
| Witch Hazel | 4 |
| Zelkova | 70 |

| | |
|------------------------|-----|
| Total A Priority Trees | 171 |
| Total B Priority Trees | 41 |
| Total C Priority Trees | 31 |
| Total Priority Trees | 243 |

| | |
|--|------------|
| Worked on in 2022 | |
| Worked on in 2021 | |
| Worked on in 2020 | |
| Road Tree is On | |
| Tree ID Tag Number | |
| (Diameter 4.5' above grade) | |
| Common Name | |
| Address Number | |
| Street Name | |
| Approximate Location | |
| Priority Rating: | |
| Size of material to be removed 1-3. 1 is smallest size | |
| Remove Tree; Haul all debris | |
| Crown Clin Dead ___" and Lgrs | |
| Structure prune to remove crossing/crowded branch unions and where needed co-dominant lead correction | |
| End weight reduce over-extended limbs likely to fail | |
| Install total of ___ direct cable systems for supplemental support of weak attachments | |
| Remove Broken Leads, Hangers and / or stubs | |
| Crown Raise over Road & Parking to Approx. 12' | |
| Crown Raise to Approx. 6-8' over Walk / Lawn / Roof / Lights | |
| Remove all upright watersprouts and train horizontal | |
| Major Health Decline / Dead | |
| Decay and/or Hollow Detected | |
| Multiple trunks | |
| Included Bark | |
| Girdling Roots | |
| Additional Notes | |
| Total Trees | 407 |